# WJE

### PERSONNEL QUALIFICATIONS

# Adam Evans | Associate III



# **EDUCATION**

- George Mason University
  - Bachelor of Science, Civil and Infrastructure Engineering, 2015
  - Master of Science, Civil and Infrastructure Engineering, 2017

# **PRACTICE AREAS**

- Facade Ordinance Inspections
- Nondestructive Evaluation
- Failure/Damage Investigations
- Structural Analysis/Computer Applications
- Masonry
- Concrete Structures
- Structural Metals
- Windows/Curtain Walls/Skylights

#### **REGISTRATIONS**

■ SPRAT Level I Technician

## **PROFESSIONAL AFFILIATIONS**

- American Concrete Institute (ACI)
- American Society of Civil Engineers (ASCE)
- Delaware Valley Association of Structural Engineers (DVASE)
- International Concrete Repair Institute (ICRI)
- Society of Professional Rope Access Technicians (SPRAT)
- Structural Engineering Institute (SEI)

#### CONTACT

aevans@wje.com 215.567.0703 www.wje.com

#### **EXPERIENCE**

Adam Evans has extensive experience in the investigation, evaluation, and rehabilitation of various wood, masonry, concrete, and steel structures. He has assisted in the design and testing of new and existing building enclosures and has conducted property and facade condition assessments.

Prior to joining WJE in 2019, Mr. Evans specialized in the nonlinear design of structural systems to resist the effects of blast and impact loading environments for private and public sector buildings. He gained proficiency in analytical modeling, retrofit design, structural detailing, and construction administration services on contemporary and historic buildings.

# **REPRESENTATIVE PROJECTS**

### **Facade Ordinance Inspections**

- Two Liberty Place Philadelphia, PA: City of Philadelphia facade inspection for stone and curtain wall facade
- Loews Philadelphia (PSFS Building) -Philadelphia, PA: City of Philadelphia facade inspection for brick, stone, and curtain wall facade
- Jewish Community Services Building -Philadelphia, PA: City of Philadelphia facade inspection for brick, stone, and curtain wall facade

# **Nondestructive Evaluation**

- Pencoyd Bridge Philadelphia, PA: Ultrasonic testing of fracture critical members
- 2301 Chestnut Street Philadelphia, PA: As-built survey of reinforcement for structural modifications using ground penetrating radar (GPR)
- State Route 54 Over Susquehanna River -Montgomery, PA: Coring oversight and location layout using GPR

# **Failure/Damage Investigations**

- Municipal Services Building Philadelphia,
  PA: Investigation of cracked granite veneer
- Philadelphia Family Court PA: Investigation of delaminated aluminum composite material metal panel rainscreen assembly
- Quantico Middle High School Quantico, VA: Investigation of voids in insulated concrete form walls

# **Structural Analysis/Computer Applications**

- 3000 C Street Philadelphia, PA: Structural analysis of boiler room for rehabilitation
- Heinz Memorial Chapel Pittsburgh, PA:
  Structural analysis of roof framing to support scaffolding for rehabilitation
- Greenwich American Center Greenwich, CT: Structural analysis of proposed window wall assembly

# Masonry

- 1320 West Somerville Avenue Philadelphia,
  PA: Inspection of composite masonry facades using industrial rope access
- Harrisburg Military Post Harrisburg, PA:
  Condition assessment of brick facades
- 12 West 17th Street New York, NY: Analysis of concrete masonry unit backup for rebuilt parapet wall

### **Concrete Structures**

- Samuel S. Baxter Water Treatment Plant -Philadelphia, PA: Crack investigation of precast double tees
- Jefferson Frankford Hospital Philadelphia,
  PA: Rehabilitation of parking garage structure
- Two Bala Plaza Bala Cynwyd, PA:
  Rehabilitation of parking garage structure

#### Structural Metals

- One Liberty Place Philadelphia, PA:
  Oversight of inspection to complete joint penetration welds located on the spire
- 500 Walnut Street Philadelphia, PA: Inspection of metal pool shell
- Coleytown Middle School Westport, CT: Assessment of steel roof framing for new rooftop unit placement

# Windows/Curtain Walls/Skylights

- Glass Facade Philadelphia, PA: Condition assessment of unitized glass curtain wall
- Williamsport Regional Airport -Montoursville, PA: Leakage investigation of building facades
- Hurricane Damage Investigations Various Locations, U.S.: Inspection of suspected hurricane damage of windows and sliding glass doors

